

---

**Appendix A4**  
**Hazardous Materials Inspection Report**

---



# TDK METRO TERMINALS UPGRADE PROJECT - HAZARDOUS MATERIALS INSPECTION REPORT

*Prepared for:*

**TDK METRO TERMINALS**  
480 AUDLEY BOULEVARD  
DELTA, BC  
CANADA, V3M 5S4

*Prepared by:*

**HATFIELD CONSULTANTS LLP**  
#200 - 850 HARBOURSIDE DRIVE  
NORTH VANCOUVER, BC  
CANADA V7P 0A3  
TEL: 1.604.926.3261 • [WWW.HATFIELDGROUP.COM](http://WWW.HATFIELDGROUP.COM)

**JANUARY 2023**

MOTT11659  
VERSION 1.0

# TABLE OF CONTENTS

|   |     |
|---|-----|
| LIST OF FIGURES.....  | ii  |
| LIST OF APPENDICES .....  | ii  |
| LIST OF ACRONYMS.....   | iii |
| EXECUTIVE SUMMARY.....  | iv  |
| DISTRIBUTION LIST .....   | v   |
| AMENDMENT RECORD .....  | v   |
| 1.0 INTRODUCTION .....  | 1   |
| 2.0 PROJECT OVERVIEW .....  | 1   |
| 3.0 SCOPE OF WORK .....   | 3   |
| 4.0 LIMITATIONS .....   | 3   |
| 5.0 FACILITY DESCRIPTION .....  | 3   |
| 6.0 METHODOLOGY .....   | 3   |
| 6.1 ASBESTOS CONTAINING MATERIALS .....   | 4   |
| 6.2 LEAD FINISHES .....   | 4   |
| 6.3 LEAD CONSTRUCTION MATERIALS, PCB, MERCURY, STORED<br>CHEMICALS, AND SILICA..... | 4   |
| 7.0 FINDINGS .....  | 4   |
| 7.1 ASBESTOS CONTAINING MATERIALS .....   | 5   |
| 7.1.1 Gypsum Board and Filling Compound.....  | 5   |
| 7.1.2 Other Building Materials .....  | 5   |
| 7.2 LEAD.....   | 5   |
| 7.3 PCB.....  | 5   |
| 7.4 MERCURY .....   | 6   |
| 7.5 STORED CHEMICALS AND OTHER HAZARDOUS MATERIALS.....                             | 6   |
| 7.6 SILICA.....   | 6   |
| 8.0 RECOMMENDATIONS .....   | 6   |
| 8.1 ASBESTOS CONTAINING MATERIALS .....   | 7   |
| 8.2 RECYCLABLE GYPSUM BOARD .....   | 7   |
| 8.3 LEAD.....   | 7   |
| 8.4 PCB.....  | 8   |
| 8.5 MERCURY .....   | 8   |
| 8.6 STORED CHEMICALS .....  | 8   |
| 8.7 NATURAL GAS .....   | 8   |

|      |                               |    |
|------|-------------------------------|----|
| 8.8  | SILICA.....                   | 8  |
| 9.0  | OWNER’S RESPONSIBILITIES..... | 9  |
| 10.0 | CONCLUSIONS.....              | 9  |
| 11.0 | CLOSING.....                  | 9  |
| 12.0 | REFERENCES.....               | 10 |

## LIST OF FIGURES

|          |                    |   |
|----------|--------------------|---|
| Figure 1 | Location plan..... | 2 |
|----------|--------------------|---|

## LIST OF APPENDICES

|            |  |  |
|------------|--|--|
| Appendix 1 | Pre-Demolition Hazardous Materials Building Survey |  |
|------------|--|--|

## LIST OF ACRONYMS

|               |   |
|---------------|---|
| <b>BC</b>     | British Columbia                              |
| <b>CFC</b>    | Chlorofluorocarbons                           |
| <b>HID</b>    | High-intensity discharge                      |
| <b>HMS</b>    | Hazardous materials survey                    |
| <b>LBP</b>    | Lead based paint                              |
| <b>OHS</b>    | Occupational Health and Safety                |
| <b>PCB</b>    | Polychlorinated biphenyls                     |
| <b>PER</b>    | Project and Environmental Review              |
| <b>PPM</b>    | Parts per million                             |
| <b>TCLP</b>   | Toxicity Characteristic Leaching Procedure    |
| <b>TEU</b>    | Twenty-foot equivalent units                  |
| <b>TDK</b>    | TDK Logistics Inc.                            |
| <b>US EPA</b> | United States Environmental Protection Agency |
| <b>VFPA</b>   | Vancouver Fraser Port Authority               |
| <b>WCB</b>    | WorkSafeBC                                    |

## EXECUTIVE SUMMARY

Hatfield Consultants (Hatfield), has been retained by TDK Logistics Inc. (TDK) Metro Terminals to prepare a Hazardous Materials Inspection Report for the Vancouver Fraser Port Authority (VFPA) Project and Environmental Review (PER) permit application. TDK is requesting a permit from the VFPA in order to upgrade their facility located at 480 Audley Boulevard, in Delta British Columbia (BC) (the Project site).

The Pre-Demolition Hazardous Building Materials Survey Report by Astech Consultants Ltd. (Astech) Pre-summarizes the findings of the site survey and sampling. The report is included in Appendix 1.

The hazardous materials survey (HMS) was conducted on October 13, 17, 18, 19, and 20, 2022 by Astech. The area assessed was limited to the multi-tenant office and warehouse/storage building. The assessment included areas of the ground floor, upper floor, both exterior, and interior.

The HMS identified asbestos-containing materials, lead finishes, lead construction materials, polychlorinated biphenyls (PCBs), mercury, stored chemicals, and silica within the building. The recommendations contained within this report should be followed prior to and during demolition of the building to mitigate potential effects from the identified hazardous materials.

The HMS was conducted while the building was still occupied and therefore was non-destructive. No attempt was made to investigate concealed or inaccessible areas, or roofing materials that would require damaging or dismantling portions of the building. Due to the non-destructive nature of the testing survey, additional testing will be required just prior to demolition.

Prior to demolition of the building, hazardous materials shall be removed and disposed of by a qualified hazardous materials abatement contractor in accordance with the WorkSafeBC (WCB) Occupational Health and Safety Regulation.

## DISTRIBUTION LIST

The following individuals/firms have received this document:

| Name           | Firm                 | Hardcopies | Email | FTP |
|----------------|----------------------|------------|-------|-----|
| Tish Kumar     | TDK Metro Terminals  | -          | ✓     | -   |
| Tegan Smith    | Channel Consulting   | -          | ✓     | -   |
| Andrew Wells   | Mott Macdonald Group | -          | ✓     | -   |
| Stuart Riddick | Mott Macdonald Group | -          | ✓     | -   |

## AMENDMENT RECORD

This report has been issued and amended as follows:

| Issue | Description  | Date     | Approved by   |
|-------|--|----------|---|
| 1     | First version of TDK Metro Terminals Upgrade Project - Hazardous Materials Inspection Report | 20230131 | <br>(Stewart Wright)<br>Project Director |
|       |  |          | <br>(Lianne Leblond)<br>Project Manager |

## 1.0 INTRODUCTION

TDK Logistics Inc. (TDK) Metro Terminals is requesting a permit from the Vancouver Fraser Port Authority (VFPA) under the Project and Environmental Review (PER) process to upgrade their facility located at 480 Audley Boulevard, in Delta British Columbia (BC) (the Project site). The VFPA is responsible for the administration, management, and control of land and water within its jurisdiction. The PER process applies to all proposed physical works and activities on federal lands and waters that are partially or wholly within VFPA's jurisdiction. The Project site is located entirely on VFPA managed federal lands and TDK has an existing lease agreement for the Project site for container storage and goods transportation operations.

The proposed Project includes upgrades to the existing container storage and transport facility to accommodate increasing market demand for goods transport and container storage.

A hazardous materials survey (HMS) was conducted by Astech Consultants Ltd. (Astech) on October 13, 17, 18, 19, and 20, 2022 in order to assess the potential for hazardous materials in the office and warehouse building which is slated for demolition. The assessment included non-destructive testing of the interior ground floor, upper floor, and exterior.

The report titled *Pre-demolition Hazardous Building Materials Survey of the Occupied Multi-tenant Warehouse/Storage Building at 480 Audley Boulevard, Delta, BC*, dated October 27, 2022, summarizes the HMS and sampling and is in Appendix 1.

A Location Plan is provided in Figure 1.

## 2.0 PROJECT OVERVIEW

The proposed Project includes upgrades to their existing container storage and transport facility to and will increase TDK's container capacity from annual throughput of 120,000 to 150,000 twenty-foot equivalent units (TEU) and will allow the facility to accommodate a greater number of trucks, increasing from 65,000 to 80,000 gate transactions per month. Investing in additional infrastructure will allow for greater operational efficiency and additional services including rail. The proposed Project will consist of:

- Demolition of the existing warehouse;
- Reconfiguration of the existing container yard and truck gate;
- Two new rail tracks to accommodate rail operations; and
- Agri transload and related infrastructure.

Construction will start in 2024 and the Project will be fully operational by 2026.





**Figure 1 Location plan.**



**Legend**

-  Project Site
-  VFPA Boundary
-  Hazardous Materials Survey Location

Data Sources:  
 a) Proposed work limit, Mott MacDonald 2022.  
 b) Hazardous materials survey location, digitized by Hatfield, 2023.  
 c) VFPA boundary, Port of Vancouver 2018.  
 c) 10 cm image, 13 April 2021, Esri Online Service.



Scale: 1:3,000  
 Projection: NAD 1983 UTM Zone 10N



### 3.0 SCOPE OF WORK

The assessment was performed to establish the location and type of hazardous building materials within the warehouse structure and its finishes. The assessment included areas of the ground floor, upper floor, both levels, exterior, and interior. Hazardous materials testing included in the HMS were:

- Asbestos-containing materials;
- Lead finishes;
- Lead construction materials;
- PCBs;
- Mercury;
- Stored chemicals; and
- Silica.

### 4.0 LIMITATIONS

The Astech survey and report format was designed specifically to satisfy the current applicable regulation from the WCB Occupation Health and Safety Regulation 20.112 (OHS Regulation) regarding hazardous building material assessments by Qualified Person for buildings and structures.

The HMS was conducted by Astech on October 13, 17, 18, 19, and 20, 2022. The survey was conducted on the subject building, and its finishes on the Project site.

The HMS was non-destructive and conducted while the building was still occupied. No attempt was made to investigate concealed or inaccessible areas, or roofing materials that would require damaging or dismantling portions of the building. Due to the non-destructive nature of the testing survey, additional testing will be required just prior to or during demolition.

### 5.0 FACILITY DESCRIPTION

The assessed area was the two-storey multi-tenant office and warehouse/storage building which was constructed in 1969. The building has had several renovations/tenant improvements over the years and is heated by rooftop air-handling units. At the time of the survey, the interior and exterior of the building were in good condition. The assessment included areas of the ground floor, upper floor, both levels, exterior, and interior.

### 6.0 METHODOLOGY

This section describes the methodologies used for the HMS to collect information and samples. All survey and sampling activity was conducted in accordance with the OHS Regulation.

## 6.1 ASBESTOS CONTAINING MATERIALS

A visual inspection was undertaken to determine the type, and location, of potential asbestos containing building materials located at the subject building. During the HMS one hundred thirty-six (136) bulk samples of potential asbestos containing materials were collected from the building. The number of samples collected during this survey was in accordance with the guidelines established by the WCB in their 2020 publication Safe Work Practices for Handling Asbestos and informed by actual site conditions. The samples collected were submitted for analysis at Astech's in-house laboratory in accordance with the WCB Occupational Health and Safety Regulation, utilizing polarized light microscopy, and dispersion staining techniques. Astech's survey observations and laboratory analytical results of asbestos-containing building materials are outlined by floor level and unit number descriptions listed in the Astech report (see Appendix 1).

## 6.2 LEAD FINISHES

A visual inspection was undertaken in order to determine the type and location of paints, primers, coatings, and/or glazing finishes suspected of containing lead at the subject building. During the HMS twelve (12) bulk samples of potential lead based paints (LBPs) were collected from the building. The samples collected were submitted for analysis at Astech's in-house laboratory in accordance with US Environmental Protection Agency Analytical Method 6200 (United States Environmental Protection Agency [US EPA], 2007) methods and the requirements of the WCB Occupational Health and Safety Regulation. Building materials with LBPs, primers, or glazing finishes are described in the Astech report (see Appendix 1).

## 6.3 LEAD CONSTRUCTION MATERIALS, PCB, MERCURY, STORED CHEMICALS, AND SILICA

A visual inspection was undertaken at the subject building to determine the presence of:

- Construction materials suspected of containing lead and other heavy metals;
- Fluorescent and high-intensity discharge (HID) light fixtures suspected of containing PCB ballasts or capacitors;
- Thermostats, light tubes/bulbs, and associated equipment suspected of containing mercury;
- Stored chemicals suspected of being toxic, flammable, or explosive; and
- Building materials suspected of containing silica in crystalline and non-crystalline forms.

## 7.0 FINDINGS

Findings from the laboratory analysis and Project site observations are summarized for each hazardous material in the Astech report (see Appendix 1). Information about the condition of the materials, and the sample or visual observation, with approximate locations, is included for each hazardous material that will be encountered during demolition. Approximate quantities of the hazardous materials and the Asbestos bulk sample report are in the Astech report (see Appendix 1, Section 7.0).

## 7.1 ASBESTOS CONTAINING MATERIALS

The visual inspection and analytical results determined that asbestos containing materials and/or potential asbestos containing materials were observed throughout the ground floor, the upper floor, and the building exterior. The results are outlined in the Astech report (see Appendix 1, Section 4.1).

### 7.1.1 Gypsum Board and Filling Compound

The site investigation and laboratory analysis of other representative samples determined that there is asbestos containing filling compound on older gypsum board (installed between approximately 1964 and 1979). Analytical results for some of the gypsum boarding filling compound samples indicated they were non-asbestos containing because of renovations conducted in the 1980s or later. Astech observed some newer gypsum board with non-asbestos filling compound fastened directly to or abutting the older gypsum board with asbestos containing filling compound.

Some of the potentially asbestos containing filling compound and affected gypsum board were concealed behind and/or abutting wood, cove base, concrete block, ceramic tiles, grouts, mortars, adhesives, and other building materials that are contaminated with the asbestos containing filling compound. There was also asbestos containing filling compound and residues on and within electrical junction boxes and other building materials where the finished gypsum board is located. Additionally, asbestos containing filling compound residue was observed on floors (concealed beneath carpets, wood laminate, and other flooring materials, plumbing fixtures, millwork, and other building materials).

### 7.1.2 Other Building Materials

Some potential asbestos containing building materials were not tested at the time of the survey due to building occupancy and the non-destructive testing. Building materials not tested must be considered to be asbestos containing until laboratory results determine otherwise. In order to sample the materials future destructive testing will be required once the building is no longer being utilized.

## 7.2 LEAD

The visual inspection and laboratory analytical results determined the following occurrences or potential occurrences of lead at the Project site. Paint finishes containing lead were observed on both the interior and exterior of the building. Ceramic tiles with glazing finishes that may contain lead were also observed, and there is potential for lead roof jacks, to be present on the roof structure.

WCB does not define a safe level for a lead-containing surface coating material. Additional testing for Toxic Characteristic Leachate Procedure (TCLP) lead testing may be required to determine the potential for soil or groundwater contamination, if deemed necessary by the site receiving the waste.

Results of LPB testing are outlined in the Astech report (see Appendix 1, Section 4.2).

## 7.3 PCB

The visual inspection determined that there are approximately one thousand two hundred (1,200) fluorescent and HID light fixtures at the subject building suspected of having one or more PCB containing

ballasts/capacitors. PCB ballast/capacitor identification requires the disassembly of the light fixture in order to locate the manufacturer's identification code.

## 7.4 MERCURY

The visual inspection determined that there is one wall mounted thermostat at the subject building that contains mercury. There are also numerous fluorescent light tubes/bulbs at the subject building that contain mercury.

## 7.5 STORED CHEMICALS AND OTHER HAZARDOUS MATERIALS

- Containers of paint, cleaners, and rodent poison;
- Fire extinguishers;
- Batteries in emergency lighting and alarm system;
- Compressors and piping with suspect ozone depleting substances (i.e., chlorofluorocarbons [CFC's]) in refrigerators, water;
- Coolers, and air handling units;
- Smoke detector(s) with a radioactive component within; and
- Piping containing natural gas leading to heating equipment.

## 7.6 SILICA

All concrete, cement, gypsum board, ceramic tile, grout, mortar, and any other cementitious building materials at the subject building are suspected of containing silica in crystalline and non-crystalline forms.

## 8.0 RECOMMENDATIONS

Due to the non-destructive nature of the testing survey, further testing will be required just prior to or during demolition. Specifically, no attempt was made to investigate concealed or inaccessible areas, or roofing materials that would require damaging or dismantling portions of the building. It is recommended that once the building is unoccupied, the remaining work should be conducted. This includes some interior destructive testing, as well as sampling of the roof.

For the storage, handling, and recycling of hazardous building materials it is recommended the work be conducted by a qualified hazardous abatement contractor in accordance with WCB Occupational Health and Safety Regulation (WCB 2017).

The abatement contractor shall prepare an exposure control plan and performance specifications for hazardous material removal required for the planned work and be responsible for assessing the risk for each hazardous material. The performance specifications should include the scope of work, safe work practices, personal protective equipment, respiratory protection, and disposal of waste materials. This report should be provided along with detailed plans and specifications to the contractor prior to commencing the work.

Recommendations for specific hazardous materials are outlined in the following sections.

## 8.1 ASBESTOS CONTAINING MATERIALS

Prior to demolition of a building, the asbestos containing materials (or potential asbestos containing materials) must first be removed and disposed of by a qualified hazardous materials abatement contractor in accordance with the WCB Occupational Health and Safety Regulation. Disposal of asbestos containing materials must be performed in accordance with the *Environmental Management Act*, Hazardous Waste Regulation.

## 8.2 RECYCLABLE GYPSUM BOARD

Prior to the demolition of a building, the gypsum board with no asbestos finishes (a provincially regulated construction waste) must first be removed by a qualified contractor and be recycled or disposed of in accordance with the BC Ministry of Environment and Climate Change Strategy – *Environmental Management Act* - Hazardous Waste Regulation. Landfills are issued operational certificates from the BC Ministry of Environment, and for local landfills and others, their certificate specifies that gypsum board cannot be accepted for disposal, and therefore local depots offer recycling services.

## 8.3 LEAD

Where lead (or potential lead) LBP and/or primers are affected by a project, the work must be performed by a qualified contractor in accordance with the WCB Occupational Health and Safety Regulation and their 2020 publication entitled *Safe Work Practices for Handling Lead* (WCB 2020).

Where the base substrate material is to be removed in conjunction with LBP removal, the base substrate and LBP and/or primers should be removed intact by the contractor, in accordance with the contractor's risk assessment and site specific work procedures. The workers conducting the work and workers in close proximity to the work being performed should be protected with personal protective equipment as determined by the contractor's risk assessment and site specific work procedures.

Lead containing paints that remain attached to wood and/or other building materials must be labeled as LBP for transporting to a licensed/approved disposal site or recycling facility. A licensed/approved facility receiving the waste must be informed of the lead content of these materials and be agreeable to receiving these materials. Prior to acceptance of waste with LBP at a licensed/ approved disposal facility, the contractor generating the waste must ensure that all waste materials containing LBPs are sampled intact, fastened directly to the base substrate, and representative of the waste stream created by demolition. The contractor shall have the representative sample analyzed for TCLP lead tests to determine the potential for soil and/or groundwater contamination if deemed necessary by the site receiving the waste.

If the LBP are to be separated or removed from the building materials by means of sanding, scraping, abrading, blasting, etc., more stringent work procedures would apply. The removed LBP, depending on lead concentrations and leachate results, may become a hazardous waste, and therefore must be disposed of in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

Where ceramic tiles with lead (or potential lead) glazing finishes are to be removed, the ceramic tile and glazing finish should be removed intact. The workers conducting the work and workers in close proximity to the work being performed, should be protected with personal protective equipment as determined by the removal contractor's risk assessment and site specific work procedures. Ceramic tiles and glazing finishes that are removed intact may be disposed of as normal construction waste. If the lead glazing finishes are to be separated or removed from the ceramic tiles by means of sanding, scraping, abrading, blasting, etc., more stringent work procedures by a qualified abatement contractor would apply in order to satisfy the WCB Occupational Health and Safety Regulation and their 2020 publication entitled Safe Work Practices for Handling Lead (WCB 2020).

Prior to demolition of the building, the lead roof jacks must first be removed, and be recycled or disposed of, in accordance with the BC Ministry of Environment and Climate Change Strategy – Environmental Management Act - Hazardous Waste Regulation.

## **8.4 PCB**

It is recommended that the identification of PCB ballasts/capacitors be performed by qualified personnel prior to or in conjunction with the demolition of a building, at a time when it becomes feasible to isolate electrical power and disassemble/disconnect the light fixtures. The ballasts/capacitors that are identified as PCB containing must be removed in accordance with the WCB Occupational Health and Safety Regulation and disposed of in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

## **8.5 MERCURY**

Prior to demolition of a building, the mercury containing thermostats and light tubes/bulbs must first be removed, and be salvaged, recycled, or disposed of, in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

## **8.6 STORED CHEMICALS**

Prior to demolition of a building, stored chemicals, ozone depleting substances within refrigeration equipment, and radioactive equipment must first be removed, and be recycled or disposed of, in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

## **8.7 NATURAL GAS**

The natural gas must be shut off and purged by Fortis BC or a qualified trades person prior to work that would affect the gas, and prior to building demolition.

## **8.8 SILICA**

Where cementitious building materials that are suspected of containing silica in crystalline form are directly impacted by the project (i.e. drilling, cutting, abrading, etc.), the work should be performed in a controlled manner to avoid the release of crystalline silica dust. Cutting, drilling, or otherwise disturbing these building

materials must be performed by a qualified contractor's trained personnel in accordance with the WCB Occupational Health and Safety Regulation (WCB, 2017).

## **9.0 OWNER'S RESPONSIBILITIES**

TDK Metro Terminals is responsible for the remediation of hazardous building materials, contract specifications, quality control, and final acceptance of the work. The building demolition will be performed by a qualified and properly insured hazardous materials abatement contractor (who can provide proof of necessary asbestos inclusion insurance rider). As well, any asbestos abatement work conducted by the contractor's trained and authorized personnel should be inspected and air-monitored daily.

## **10.0 CONCLUSIONS**

The hazardous materials identified in the HMS were asbestos-containing materials, lead finishes, lead construction materials, PCBs, mercury, stored chemicals, and silica which were either suspected or found throughout the ground floor, upper floor, both levels, exterior and interior of the building at the Project site.

Due to the non-destructive nature of this testing survey, further investigation prior to or during demolition is required for concealed or inaccessible areas and roofing materials that require damaging or dismantling portions of the building. The recommendations identified in Section 8.0 should be followed prior to and during demolition of the building.

## **11.0 CLOSING**

This report has been prepared by Hatfield, with information provided by Astech and has assumed that the information provided is both complete and accurate. This work was performed to current industry standard practice and the findings presented in this report should be considered within the context of the scope of work and Project terms of reference. The findings are time sensitive and are true only at the time the report was produced. The conclusions and recommendations contained in this report are based upon applicable guidelines, regulations, and legislation existing at the time the report was produced. If there are any changes to regulatory criteria, the conclusions and/or recommendations may require updating.



## 12.0 REFERENCES

[US EPA] US Environmental Protection Agency. 2007. Method 6200 - Field Portable X-Ray Fluorescence Spectrometry for the Determination of Elemental Concentrations in Soil and Sediment.

[WCB] Workers' Compensation Board of British Columbia. 2017. Occupational Health and Safety (OHS) Regulation, BC Reg. 296/97, including Reg. 142/2017, App A amendments.

[WCB] Workers' Compensation Board of British Columbia. 2020. Safe Work Practices for Handling Lead. Available at: <https://www.worksafebc.com/en/resources/health-safety/books-guides/safe-work-practices-handling-lead?lang=en>

---

## **APPENDICES**

---

---

**Appendix 1**

**Pre-Demolition Hazardous Materials  
Building Survey**

---



October 27, 2022

## **TDK METRO TERMINALS**

#10-480 Audley Blvd  
Delta, BC V3M 4S4

Attention: Tish Kumar, Vice President  
TDK Logistics Ltd.

**Ref: CONTRACTOR VERSION - PRE-DEMOLITION HAZARDOUS BUILDING MATERIALS SURVEY OF THE OCCUPIED MULTI-TENANT WAREHOUSE/STORAGE BUILDING LOCATED AT 480 AUDLEY BOULEVARD, DELTA, BC**

## **1.0 INTRODUCTION**

Astech Consultants Ltd. (Astech) were retained by TDK Metro Terminals to conduct a Pre-Demolition Hazardous Building Materials Survey and compile a detailed report on the presence and location of asbestos containing building materials, lead, polychlorinated biphenyls (PCBs), mercury, stored chemicals, and silica at the Occupied Multi-Tenant Warehouse/Storage Building located at 480 Audley Boulevard, Delta, BC.

Astech's survey and report format is designed specifically to satisfy the current applicable regulation from the Workers' Compensation Board of British Columbia (WCB) Occupational Health and Safety Regulation 20.112 regarding hazardous building material assessments by a Qualified Person for buildings and structures.

This initial phase survey was conducted on October 13, 17, 18, 19, and 20, 2022 by Trevor Shendruk assisted by Andrew Henning of Astech. It must be emphasized that this survey was concerned exclusively with the subject building. The initial phase survey was conducted while the building is still occupied and therefore was non-destructive in nature and, for the most part, included for representative sampling from inconspicuous locations of the building. No attempt was made to investigate concealed and/or inaccessible areas, or roofing materials which would require damaging or dismantling portions of the building. No attempt was made to investigate underground services or the surrounding property. Therefore, if during work activities, other hazardous materials, asbestos containing materials, or potential asbestos containing materials not included in this report are discovered, work should immediately cease in the affected area. At that time, Astech should be contacted so that they can initiate immediate appropriate action so that there are no undue delays.

## **2.0 BUILDING DESCRIPTION**

The subject building on site is described as a two-storey plus basement multi-tenant office and warehouse/storage building faced with concrete block. According to BC Assessment, the building was originally constructed in 1969. The building has had several renovations/tenant improvements over the years. The building is heated by rooftop air handling units. At the time of survey, the interior and exterior of the building were in good condition, with the exception of a few areas with small amounts of asbestos containing loose fill vermiculite insulation debris on floors in Unit #10.

## 3.0 METHODOLOGY

### 3.1 ASBESTOS CONTAINING MATERIALS

A visual inspection was undertaken in order to determine the type, location, and homogeneous nature of asbestos and potential asbestos containing building materials located at the subject building. During this inspection, one hundred thirty-six (136) bulk samples of potential asbestos containing materials were collected from specific locations of the building. The number of samples collected during this survey are in accordance with the guidelines established by the WCB in their 2020 publication Safe Work Practices for Handling Asbestos, and as indicated by actual site conditions. The samples collected were submitted for analysis at our in-house laboratory in accordance with the WCB Occupational Health and Safety Regulation, utilizing polarized light microscopy, and dispersion staining techniques. Results of laboratory analysis of the samples collected during this survey are attached.

### 3.2 LEAD FINISHES

A visual inspection was undertaken in order to determine the type and location of paints, primers, coatings, and/or glazing finishes suspected of containing lead at the subject building. During this inspection, twelve (12) bulk samples of potential lead finishes were collected from specific locations of the building. The samples collected were submitted for analysis at our in-house laboratory in accordance with US EPA methods and the requirements of the WCB Occupational Health and Safety Regulation. Results of laboratory analysis of the samples collected during this survey are attached.

### 3.3 LEAD CONSTRUCTION MATERIALS, PCBs, MERCURY, STORED CHEMICALS, AND SILICA

A visual inspection was undertaken at the subject building in order to determine the presence of:

- construction materials suspected of containing lead and other heavy metals,
- fluorescent and high intensity discharge (HID) light fixtures suspected of containing PCB ballasts or capacitors,
- thermostats, light tubes/bulbs, and associated equipment suspected of containing mercury,
- stored chemicals suspected of being toxic, flammable, or explosive, and
- building materials suspected of containing silica in crystalline and non-crystalline forms.

## 4.0 INSPECTION RESULTS

### 4.1 ASBESTOS CONTAINING MATERIALS

#### GENERAL NOTES

**#1 Filling Compound and Affected Gypsum Board:** Although the analytical results for some of the gypsum board filling compound samples indicate non-asbestos results because of renovations conducted in the 1980s or later, site investigation and laboratory analysis of other representative samples have determined that as listed below, there is asbestos containing filling compound on older gypsum board (installed between approximately 1964 and 1979), or there is newer gypsum board with non-asbestos filling compound fastened directly to or abutting the older gypsum board with asbestos containing filling compound (some multi-layered and some concealed behind wood and other building materials).

As well, some of the asbestos containing filling compound and affected gypsum board are concealed behind and/or abutting wood, cove base, concrete block, ceramic tiles, grouts, mortars,

adhesives, and other building materials that are contaminated with the **asbestos** containing filling compound. There is also **asbestos** containing filling compound and **asbestos** containing filling compound residue on and within electrical junction boxes and other building materials where finished gypsum board is located.

Additionally, there is **asbestos** containing filling compound residue on floors (concealed beneath carpets, wood laminate, and other flooring materials, plumbing fixtures, millwork, and other building materials).

**#2 Potential Asbestos Containing Building Materials:** The potential **asbestos** containing building materials listed below were not tested at time of survey due to building occupancy and must be considered to be **asbestos** containing until laboratory results determine otherwise. In order to sample the materials future destructive testing will be required, once the building is no longer being utilized.

The visual inspection and/or analytical results determined that asbestos containing materials and/or potential asbestos containing materials are located at the following specific locations.

#### **GROUND FLOOR**

##### **Unit #4 - Open Office Area including Reception**

- Potential **asbestos** containing building materials which may be beneath carpet (see General Note #2 above).
- Potential **asbestos** containing ceramic floor tile grout and mortar on potential **asbestos** containing building materials (see General Note #2 above).

##### **Unit #4 - Sprinkler Room**

- No asbestos materials observed.

##### **Unit #4 - Entire Open Warehouse**

- **Asbestos** containing pipe thread compound at fittings of natural gas piping (mostly concealed).

##### **Unit #4 - Northeast Office, and**

##### **Unit #4 - Stairwell to Upper Floor**

- Potential **asbestos** containing building materials which may be beneath carpet (see General Note #2 above).

##### **Unit #4 - Washroom,**

##### **Unit #4 - Washroom within Warehouse, and**

##### **Unit #4 - Office within Warehouse including Closet**

- No asbestos materials observed.

##### **Unit #8 - Entire Open Warehouse**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing pipe thread compound at fittings of natural gas piping (mostly concealed).

##### **Unit #8 - South Open Area within Warehouse,**

##### **Unit #8 - Southeast Storage Room within Warehouse,**

##### **Unit #8 - Three Adjoining Southeast Offices,**

##### **Unit #8 - Telecom Room, and**

##### **Unit #8 - Southeast Offices**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).

**Unit #8 - South Office within Open Office Area,  
Unit #8 - Southwest Hallway,  
Unit #8 - South Break Room  
Unit #8 - First Aid Room, and  
Unit #8 - Centre North Office including Closet, and  
Unit #8 - Four adjoining North Offices**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).

**Unit #8 - South Office within Warehouse**

- **Asbestos** containing floor tiles (concealed beneath a layer of carpet, non-asbestos floor tiles, non-asbestos floor tile adhesive, and other building materials).
- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).

**Unit #8 - North Open Area within Warehouse**

- **Asbestos** containing floor tiles (concealed beneath a layer of non-asbestos sheet flooring and other building materials).
- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing mastic on joints of ductwork (some concealed).

**Unit #8 - Three adjoining West Offices within Warehouse**

- **Asbestos** containing floor tiles (concealed beneath a layer of carpet and other building materials).
- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing insulating cement at fittings of mechanical piping (some concealed).

**Unit #8 - Two Adjoining Northeast Storage Rooms within Warehouse**

- **Asbestos** containing floor tiles (concealed beneath a layer of non-asbestos sheet flooring and other building materials).
- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).

**Unit #8 - Mechanical Room within Warehouse**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing pipe thread compound at fittings of natural gas piping (mostly concealed).
- **Asbestos** containing insulating cement at fittings of mechanical piping (some concealed).
- Potential **asbestos** containing paper insulation lining interior of metal exhaust vents to rooftop (see General Note #2 above).

**Unit #8 - East Front Entrance Foyer**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- Potential **asbestos** containing ceramic floor tile grout and mortar on potential **asbestos** containing building materials (see General Note #2 above).
- Potential **asbestos** containing glass block mortar (see General Note #2 above).

**Unit #8 - South Open Office Area**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing sealant in interior wood-framed windows (mostly concealed).

**Unit #8 - Loading Bay including Office within**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing insulating cement at fittings of mechanical piping (some concealed).

**Unit #8 - South Men's and Women's Washroom, and  
Unit #8 - North Men's and Women's Washroom**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- Potential **asbestos** containing ceramic floor tile grout and mortar on potential **asbestos** containing building materials (see General Note #2 above).

**Unit #8 - North Break Room**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing coating on underside of metal sink.

**Unit #8 - North Open Office Area, and  
Unit #8 - Northeast Hallway**

- **Asbestos** containing floor tiles (concealed beneath a layer of carpet and other building materials).
- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).

**Unit #10 - South Open Warehouse including Mezzanine**

- **Asbestos** containing loose fill vermiculite insulation debris on floor (in proximity to concrete block walls).
- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing pipe thread compound at fittings of natural gas piping (mostly concealed).

**Unit #10 - Washroom within South Warehouse**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- Potential **asbestos** containing building materials which may be beneath vinyl plank flooring (see General Note #2 above).

**Unit #10 - Centre Open Warehouse**

- **Asbestos** containing loose fill vermiculite insulation debris on floor (in proximity to concrete block walls).
- **Asbestos** containing pipe thread compound at fittings of natural gas piping (mostly concealed).
- **Asbestos** containing cement drain pipe/rain water leader (some concealed).
- Potential **asbestos** containing insulation within firedoors (see General Note #2 above).

**Unit #10 - North Warehouse, and**

**Unit #10 - Stairwell to Mezzanine**

- **Asbestos** containing floor tiles (some concealed).

**Unit #10 - Mezzanine within North Warehouse**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing caulking residue on concrete block walls (some concealed and some on adjoining building materials).
- Potential **asbestos** containing building materials which may be beneath wood laminate (see General Note #2 above).

**Unit #10 - Hot Water Tank Room (Office)**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- **Asbestos** containing pipe thread compound at fittings of natural gas piping (mostly concealed).
- Potential **asbestos** containing paper insulation lining interior of metal exhaust vents to rooftop (see General Note #2 above).



**Unit #10 - Men's and Women's Washroom (Office)**

- **Asbestos** containing floor tiles (concealed beneath a layer of non-asbestos floor tiles, non-asbestos floor tile adhesive, and other building materials).
- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).

**Unit #10 - Break Room (Office),****Unit #10 - Hallway (Office),****Unit #10 - Northwest Office and Northeast Office, and****Unit #10 - South Open Office Area**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- Potential **asbestos** containing building materials which may be beneath wood laminate (see General Note #2 above).

**Unit #10 - Northeast Office**

- **Asbestos** containing filling compound on gypsum board (see General Note #1 above).
- Potential **asbestos** containing adhesive behind foam and non-asbestos gypsum board (see General Note #2 above).

**UPPER FLOOR****Unit #4 - Open Office Area,****Unit #4 - Boardroom, and****Unit #4 - Office**

- Potential **asbestos** containing building materials which may be beneath carpet (see General Note #2 above).

**Unit #4 - Break Room,****Unit #4 - Storage Room,****Unit #4 - Washroom, and****Unit #4 - Computer Room**

- No asbestos materials observed.

**BOTH LEVELS****Floor Cavities**

- No asbestos materials observed.

**Wall Cavities and Ceiling Spaces**

- **Asbestos** containing floor tiles (concealed beneath newer partition walls in proximity to where **asbestos** containing floor tiles are listed above).
- **Asbestos** containing loose fill vermiculite insulation within interior concrete block walls, and **asbestos** contaminated block and mortar.
- **Asbestos** containing pipe thread compound at fittings of natural gas piping (mostly concealed).
- **Asbestos** containing insulating cement and/or insulating cement residue on fittings of mechanical piping systems (some concealed).

**EXTERIOR****Piping**

- **Asbestos** containing pipe thread compound at fittings of natural gas piping (mostly concealed).

**Walls**

- No asbestos materials observed.

**Doors and Windows**

- **Asbestos** containing sealant in exterior metal-framed windows (mostly concealed).
- **Asbestos** containing caulking around exterior metal doors (some concealed and some on adjoining building materials).

**Rooftop**

- Potential **asbestos** containing roofing membranes, felts, mastics, caulking, sealants, and/or patching compounds (see General Note #2 above).
- Potential **asbestos** containing paper insulation lining interior of metal exhaust vents (see General Note #2 above).

**Underground**

- Potential **asbestos** containing underground cement drain pipes beneath building and throughout property (see General Note #2 above).

**4.2 LEAD****Interior**

- beige paint containing 647 parts per million (PPM) of **lead** was used on wood surfaces,
- green on blue paint containing 243 PPM of **lead** was used on wood surfaces,
- white paint containing 131 PPM of **lead** was used on wood surfaces,
- grey on blue paint containing 28 PPM of **lead** was used on concrete surfaces,
- blue paint containing 22 PPM of **lead** was used on concrete block surfaces,
- white paint containing less than (<)13 PPM of **lead** was used on concrete block surfaces,
- black paint containing <9 PPM of **lead** was used on metal bollards,
- grey paint containing <9 PPM of **lead** was used on wood surfaces, and
- off-white paint containing <8 PPM of **lead** was used on wood surfaces.

**Exterior**

- white paint containing 53 PPM of **lead** was used on concrete block surfaces,
- yellow paint containing 15 PPM of **lead** was used on concrete block and metal surfaces,
- grey paint containing 31 PPM of **lead** was used on concrete surfaces, and
- there may be **lead** roof vents and caps located on the rooftop.

**4.3 PCBs**

The visual inspection determined that there are approximately one thousand two hundred (1,200) fluorescent and HID light fixtures at the subject building suspected of having one or more PCB containing ballasts/capacitors. PCB ballast/capacitor identification requires the disassembly of the light fixture in order to locate the manufacturer's identification code.

**4.4 MERCURY**

The visual inspection determined that there is one (1) wall mounted thermostat at the subject building that contains mercury. There are also numerous fluorescent light tubes/bulbs at the subject building that contain mercury.

## 4.5 STORED CHEMICALS AND OTHER HAZARDOUS MATERIALS

- numerous containers of paint, cleaners, and rodent poison,
- numerous fire extinguishers,
- batteries in emergency lighting and alarm system,
- compressors and piping with suspect ozone depleting substances (CFC's) in refrigerators, water coolers, and air handling units,
- smoke detector(s) with a radioactive component within, and
- piping containing natural gas leading to heating equipment.

## 4.6 SILICA

All concrete, cement, gypsum board, ceramic tile, grout, mortar, and any other cementitious building materials at the subject building are suspected of containing silica in crystalline and non-crystalline forms.

## 4.7 GYPSUM BOARD

The visual inspection and/or laboratory analytical results determined the following at the subject building:

- there is **asbestos** containing filling compound on gypsum board located throughout Unit #8 and Unit #10 (see Section 4.1 including General Note #1 above), and therefore would be disposed of as mixed asbestos and gypsum waste,
- there is non-asbestos filling compound on gypsum board located throughout Unit #4, and
- there is unfinished gypsum board located in the Ground Floor Unit #8 North Break Room.

## 5.0 RECOMMENDATIONS

### 5.1 ASBESTOS CONTAINING MATERIALS

Prior to demolition of a building, the asbestos containing materials (or assumed asbestos containing materials) must first be removed and disposed of by a qualified hazardous materials abatement contractor in accordance with the WCB Occupational Health and Safety Regulation. Disposal of asbestos containing materials must be performed in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

### 5.2 LEAD

#### Paints/Primers

Where lead (or potential lead) based paints and/or primers are affected by a project, the work must be performed by a qualified contractor in accordance with the WCB Occupational Health and Safety Regulation and their 2020 publication entitled Safe Work Practices For Handling Lead.

Where the base substrate material is to be removed in conjunction with lead paint removal, the base substrate and lead based paints and/or primers should be removed intact by the contractor, in accordance with the contractor's risk assessment and site specific work procedures. The workers conducting the work and workers in close proximity to the work being performed, should be protected with personal protective equipment as determined by the contractor's risk assessment and site specific work procedures.

Lead containing paints which remain attached to wood and/or other building materials must be labelled as lead based paints (LBP) for transporting to a licensed/approved disposal site or recycling facility. A licensed/approved facility receiving the waste must be informed of the lead content of these materials and

be agreeable to receiving these materials. Prior to acceptance of waste with lead paints at a licensed/ approved disposal facility, the contractor generating the waste must ensure that all waste materials containing LBP's are sampled intact, fastened directly to the base substrate, and representative of the waste stream created by demolition. The contractor shall have the representative sample analyzed utilizing a Toxicity Characteristic Leachate Procedure for lead (TCLP lead) test to determine the potential for soil and/or groundwater contamination, if deemed necessary by the site receiving the waste.

If the lead paints are to be separated or removed from the building materials by means of sanding, scraping, abrading, blasting, etc., more stringent work procedures would apply. The removed lead paints, depending on lead concentrations and leachate results, may become a Hazardous Waste and therefore must be disposed of in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

### **Glazing Finishes**

Where ceramic tiles with lead (or potential lead) glazing finishes are to be removed, the ceramic tile and glazing finish should be removed intact. The workers conducting the work and workers in close proximity to the work being performed, should be protected with personal protective equipment as determined by the removal contractor's risk assessment and site specific work procedures. Ceramic tiles and glazing finishes that are removed intact may be disposed of as normal construction waste.

If the lead glazing finishes are to be separated or removed from the ceramic tiles by means of sanding, scraping, abrading, blasting, etc., more stringent work procedures by a qualified abatement contractor would apply in order to satisfy the WCB Occupational Health and Safety Regulation and their 2020 publication entitled Safe Work Practices For Handling Lead.

### **Lead Construction Materials**

Prior to demolition of a building, the lead roof jacks must first be removed, and be recycled or disposed of, in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

## **5.3 PCB CONTAINING BALLASTS/CAPACITORS**

It is recommended that the identification of PCB ballasts/capacitors be performed by qualified personnel prior to or in conjunction with the demolition of a building, at a time when it becomes feasible to isolate electrical power and disassemble/disconnect the light fixtures. The ballasts/capacitors that are identified as PCB containing must be removed in accordance with the WCB Occupational Health and Safety Regulation and disposed of in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

## **5.4 MERCURY**

Prior to demolition of a building, the mercury containing thermostats and light tubes/bulbs must first be removed, and be salvaged, recycled or disposed of, in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

## **5.5 STORED CHEMICALS AND OTHER HAZARDOUS MATERIALS**

### **Stored Chemicals**

Prior to demolition of a building, stored chemicals, ozone depleting substances within refrigeration equipment, and radioactive equipment must first be removed, and be recycled or disposed of, in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act* - Hazardous Waste Regulation.

## **Natural Gas**

The natural gas must be shut off and purged by Fortis BC or a qualified trades person prior to work that would affect the gas, and prior to building demolition.

## **5.6 SILICA**

Where cementitious building materials that are suspected of containing silica in crystalline form are directly impacted by the project (i.e. drilling, cutting, abrading, etc.), the work should be performed in a controlled manner to avoid the release of crystalline silica dust. Cutting, drilling, or otherwise disturbing these building materials must be performed by a qualified contractor's trained personnel in accordance with the WCB Occupational Health and Safety Regulation.

## **5.7 RECYCLABLE GYPSUM BOARD**

Prior to the demolition of a building, the gypsum board with no asbestos finishes (a provincially regulated construction waste) must first be removed by a qualified contractor, and be recycled or disposed of in accordance with the BC Ministry of Environment and Climate Change Strategy - *Environmental Management Act - Hazardous Waste Regulation*. Landfills are issued operational certificates from the BC Ministry of Environment, and for local landfills and others their certificate specifies that gypsum board cannot be accepted for disposal, and therefore local depots offer recycling services.

# **6.0 OWNER'S AND ABATEMENT CONTRACTOR'S RESPONSIBILITIES**

## **Owner's Responsibilities**

For the remediation of hazardous building materials, contract specifications, quality control, and final acceptance of the work remain the responsibility of the Owner. In order to ensure that the Owner has acted in a responsible manner, and to ensure regulatory board compliance, it is recommended that the work and project air monitoring be performed by a qualified and properly insured (with proof of necessary asbestos inclusion rider) Hazardous Materials Abatement Contractor.

## **Abatement Contractor's Responsibilities**

The Abatement Contractor upon completing the work shall have their "Qualified Person" inspect the worksite in its entirety to confirm that asbestos and other hazardous building materials have been properly removed, then promptly provide the Owner with a signed Letter of Completion.

As well, prior to transport of hazardous waste, the Abatement Contractor shall assist the Owner by completing and submitting the BC Ministry of Environment Waste Generator Number Registration Form (Schedule 5 Form 1), once signed by the Owner, if no BC Generator number exists. If a BC Generator number exists and requires updating for this specific project, the Abatement Contractor shall assist with completing and submitting the update.

Project Documentation should also be provided to the Owner including, but not necessarily limited to, a Notice of Project for work involving Asbestos and/or Lead Paint, Risk Assessment, Exposure Control Plan, and Site Specific Work Procedures, Worker Respirator Fit Test Forms/Logs and Training Acknowledgement Forms, Certification of DOP Testing of HEPA Filtered Equipment used on site, Air Sample Results, Material Safety Data Sheets (MSDS) for products used on site, Transportation Waybills, and Waste Manifest Forms.

## 7.0 APPROXIMATE QUANTITIES FOR HAZARDOUS MATERIALS

The following approximate quantities for hazardous materials are provided as a means to satisfy the requirements of the WCB, and are provided for reference only. Contractors shall be responsible for verifying exact quantities for the purpose of bidding the work.

| <b>ASBESTOS CONTAINING MATERIALS</b>   | <b>APPROXIMATE QUANTITIES</b> |
|--|-------------------------------|
| <b>Confirmed Asbestos Containing Materials</b>   |                               |
| Asbestos Floor Tiles and Contaminated Building Materials   | 4,042 square feet             |
| Asbestos Filling Compound and Residue, Affected Gypsum Board, and Other Contaminated Building Materials (including work area enclosure and air monitoring)   | 30,465 square feet            |
| Asbestos Loose Fill Vermiculite Insulation within Concrete Block Walls, Loose Fill Vermiculite Insulation Debris, and Contaminated Building Materials (including work area enclosure and air monitoring) | 6,990 square feet             |
| Asbestos Caulking Residue on Concrete Block Walls and Contaminated Building Materials  | 2 square feet                 |
| Asbestos Sealant in Interior Wood-Framed Windows   | 7 windows                     |
| Asbestos Sealant in Exterior Metal-Framed Windows  | 30 windows                    |
| Asbestos Caulking around Exterior Metal Door and Contaminated Building Materials   | 1 door                        |
| Asbestos Coating on Underside of Metal Sink  | 1 sink                        |
| Asbestos Mastic on Joints of Ductwork and Contaminated Building Materials  | 900 lineal feet               |
| Asbestos Pipe Thread Compound at Fittings of Natural Gas Piping  | 100 fittings                  |
| Asbestos Insulating Cement and/or Insulating Cement Residue on Fittings of Mechanical Piping Systems, and Asbestos Contaminated Insulations and Other Building Materials                                 | 50 fittings                   |
| Asbestos Cement Drain Pipe/Rain Water Leader   | 25 lineal feet                |
| <b>Potential Asbestos Containing Materials</b>   |                               |
| Potential Asbestos Building Materials beneath Wood Laminate (see General Note #2 in Section 4.1 above)   | 2,140 square feet             |
| Potential Asbestos Building Materials beneath Carpet (see General Note #2 in Section 4.1 above)  | 2,520 square feet             |
| Potential Asbestos Building Materials beneath Potential Asbestos Ceramic Floor Tile Grout and Mortar (see General Note #2 in Section 4.1 above)  | 200 square feet               |
| Potential Asbestos Building Materials beneath Vinyl Plank Flooring (see General Note #2 in Section 4.1 above)  | 180 square feet               |
| Potential Asbestos Glass Wall Block Mortar (see General Note #2 in Section 4.1 above)  | 20 square feet                |
| Potential Asbestos Wall Adhesive behind Foam and Non-Asbestos Gypsum Board (see General Note #2 in Section 4.1 above)  | 1,440 square feet             |
| Potential Asbestos Insulation within Metal Firedoors (see General Note #2 in Section 4.1 above)  | 2 doors                       |
| Potential Asbestos Roofing Membranes, Felts, Mastics, Caulkings, Sealants, and/or Patching Compounds (see General Note #2 in Section 4.1 above)  | Not Determined                |
| Potential Asbestos Paper Insulation Lining Interior of Metal Exhaust Vents to Rooftop (see General Note #2 in Section 4.1 above)   | 2 vents                       |
| Potential Asbestos Underground Cement Drain Pipes Beneath Building and Throughout Property (see General Note #2 in Section 4.1 above)  | Not Determined                |
| <b>OTHER HAZARDOUS MATERIALS</b>   |                               |
| Lead Paint Remaining Attached to Building Materials for Recycle/Disposal, Dependent on TCLP Lead Testing (if deemed necessary by receiving site)   | Not Determined                |
| Lead Products for Recycle (lead roof vents and caps)   | Not Determined                |
| Potential PCB Containing Ballasts/Capacitors   | 1,200 fixtures                |
| Mercury Containing Thermostats   | 1 thermostat                  |
| Mercury Containing Light Tubes/Bulbs   | 2,682 tubes/161bulbs          |

We hope you have found the above information useful. If you have any questions, or require clarification please contact this office.

Trevor Shendruk  
Astech Consultants Ltd.  
Ref: 25886HE01RC.AEH



# ASBESTOS BULK SAMPLE REPORT

Date: October 27, 2022  
 Client: TDK METRO TERMINALS  
 Location: Multi-Tenant Warehouse/Storage Building  
 480 Audley Boulevard  
 Delta, BC

Comments: 1) Asbestos (bulk) by PLM analyzed as per NIOSH 9002 Issue 2.  
 2) Workers' Compensation Board of British Columbia (WCB) defines asbestos containing material as 0.5% or more asbestos, with the exception of Vermiculite Insulation which is defined as "any asbestos".  
 3) Samples will be disposed of after 90 days, unless the Client requests otherwise.

## Sample(s) Collected on October 13, 2022

| Sample     | Location   | Description  | Layer: Colour        | Non-Asbestos |                              | Asbestos                         |      |
|------------|--|--|----------------------|--------------|------------------------------|----------------------------------|------|
|            |  |  |                      | %            | Type                         | %                                | Type |
| 25886 BS01 | Unit #10 - Ground Floor<br>- South Open Warehouse                | Paint<br>Filling Compound on<br>Gypsum Board (East Wall) | 1: White<br>2: White | 100%         | Non-Fibrous                  | None Detected                    |      |
| 25886 BS02 | Unit #10 - Ground Floor<br>- South Open Warehouse                | Concrete Block Mortar<br>(North Wall)                    | 1: Grey              | 100%         | Non-Fibrous                  | None Detected                    |      |
| 25886 BS03 | Unit #10 - Ground Floor<br>- South Open Warehouse<br>(Mezzanine) | Insulating Cement (at<br>Elbow of Mechanical<br>Piping)  | 1: Off-White         | 40%          | Glass<br>60% Non-Fibrous     | None Detected                    |      |
| 25886 BS04 | Unit #10 - Ground Floor<br>- Washroom Within<br>South Warehouse  | Cove Base  | 1: Grey              | 100%         | Non-Fibrous                  | None Detected                    |      |
| 25886 BS05 | Unit #10 - Ground Floor<br>- Washroom Within<br>South Warehouse  | Cove Base Adhesive                                       | 2: Beige             | 1%           | Cellulose<br>99% Non-Fibrous | None Detected                    |      |
| 25886 BS06 | Unit #10 - Ground Floor<br>- Centre Open<br>Warehouse            | Concrete Block Mortar<br>(North Wall)                    | 1: Grey              | 100%         | Non-Fibrous                  | None Detected                    |      |
| 25886 BS07 | Unit #10 - Ground Floor<br>- Centre Open<br>Warehouse            | Loose Fill Vermiculite<br>Insulation Debris              | 1: Brown             | 99%          | Non-Fibrous                  | 1% Actinolite                    |      |
| 25886 BS08 | Unit #10 - Ground Floor<br>- Centre Open<br>Warehouse            | Cement Drain Pipe (Rain<br>Water Leader)                 | 1: White             | 20%          | Non-Fibrous                  | 75% Chrysotile<br>5% Crocidolite |      |

| Sample     | Location   | Description  | Layer: Colour       | Non-Asbestos                                  | Asbestos             |
|------------|--|--|---------------------|---|----------------------|
|            |  |  |                     | % Type  | % Type               |
| 25886 BS09 | Unit #10 - Ground Floor<br>- North Warehouse                     | Pipe Thread Compound<br>(at Fitting of Sprinkler<br>Piping)        | 1: Black            | 2% Cellulose<br>98% Non-Fibrous               | None Detected        |
| 25886 BS10 | Unit #10 - Ground Floor<br>- North Warehouse                     | Concrete Block Mortar<br>(South Wall)                              | 1: Grey             | 100% Non-Fibrous                              | None Detected        |
| 25886 BS11 | Unit #10 - Ground Floor<br>- North Warehouse                     | Floor Tile   | 1: Off-White        | 99% Non-Fibrous                               | 1% <b>Chrysotile</b> |
| 25886 BS12 | Unit #10 - Ground Floor<br>- North Warehouse                     | Floor Tile Adhesive  | 2: Black            | 1% Cellulose<br>99% Non-Fibrous               | None Detected        |
| 25886 BS13 | Unit #10 - Ground Floor<br>- North Warehouse                     | Sealant (in Window of<br>South Interior Metal Door)                | 1: Black            | 2% Cellulose<br>98% Non-Fibrous               | None Detected        |
| 25886 BS14 | Unit #10 - Ground Floor<br>- Mezzanine Within<br>North Warehouse | 2' X 4' Ceiling Tile (Large<br>Fissures)                           | 1: Grey             | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected        |
| 25886 BS15 | Unit #10 - Ground Floor<br>- Mezzanine Within<br>North Warehouse | Caulking Residue (on<br>North Concrete Block<br>Wall, Above T-Bar) | 1: Green            | 99% Non-Fibrous                               | 1% <b>Chrysotile</b> |
| 25886 BS16 | Unit #10 - Ground Floor<br>- Mezzanine Within<br>North Warehouse | 2' X 4' Ceiling Tile<br>(Medium Fissures, 2010)                    | 1: Grey             | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected        |
| 25886 BS17 | Unit #10 - Ground Floor<br>- Mezzanine Within<br>North Warehouse | Coating (on Underside of<br>Metal Sink)                            | 1: Off-White        | 5% Cellulose<br>95% Non-Fibrous               | None Detected        |
| 25886 BS18 | Unit #10 - Ground Floor<br>- Mezzanine Within<br>North Warehouse | Paint<br>Filling Compound on<br>Gypsum Board (North<br>Wall)       | 1: Beige<br>2: Grey | 97% Non-Fibrous                               | 3% <b>Chrysotile</b> |
| 25886 BS19 | Unit #10 - Ground Floor<br>- Hot Water Tank Room<br>(Office)     | Pipe Thread Compound<br>(at Fitting of Natural Gas<br>Piping)      | 1: Blue             | 100% Non-Fibrous                              | None Detected        |
| 25886 BS20 | Unit #10 - Ground Floor<br>- Hot Water Tank Room<br>(Office)     | Pipe Thread Compound<br>(at Fitting of Natural Gas<br>Piping)      | 1: Off-White        | 97% Non-Fibrous                               | 3% <b>Chrysotile</b> |
| 25886 BS21 | Unit #10 - Ground Floor<br>- Hot Water Tank Room<br>(Office)     | Insulating Cement (at<br>Elbow of Mechanical<br>Piping)            | 1: Beige            | 40% Glass<br>60% Non-Fibrous                  | None Detected        |
| 25886 BS22 | Unit #10 - Ground Floor<br>- Hot Water Tank Room<br>(Office)     | Paint<br>Filling Compound on<br>Gypsum Board (North<br>Wall)       | 1: Blue<br>2: Grey  | 98% Non-Fibrous                               | 2% <b>Chrysotile</b> |
| 25886 BS23 | Unit #10 - Ground Floor<br>- Men's Washroom<br>(Office)          | Floor Tile   | 1: Grey             | 100% Non-Fibrous                              | None Detected        |
| 25886 BS24 | Unit #10 - Ground Floor<br>- Men's Washroom<br>(Office)          | Floor Tile Adhesive  | 2: Beige            | 100% Non-Fibrous                              | None Detected        |
| 25886 BS25 | Unit #10 - Ground Floor<br>- Men's Washroom<br>(Office)          | Floor Tile   | 3: Off-White        | 99% Non-Fibrous                               | 1% <b>Chrysotile</b> |



| Sample     | Location  | Description   | Layer: Colour | Non-Asbestos                                  | Asbestos             |
|------------|---|---|---------------|---|----------------------|
|            |   |   |               | % Type  | % Type               |
| 25886 BS26 | Unit #10 - Ground Floor<br>- Men's Washroom<br>(Office) | Floor Tile Adhesive   | 4: Black      | 2% Cellulose<br>98% Non-Fibrous               | None Detected        |
| 25886 BS27 | Unit #10 - Ground Floor<br>- Break Room (Office)        | 2' X 4' Ceiling Tile (Large<br>Fissures)                          | 1: Grey       | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected        |
| 25886 BS28 | Unit #10 - Ground Floor<br>- Break Room (Office)        | 2' X 4' Ceiling Tile (Large<br>Fissures)                          | 1: Grey       | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected        |
| 25886 BS29 | Exterior  | Paint/Coating (on West<br>Concrete Block Wall)                    | 1: Grey       | 100% Non-Fibrous                              | None Detected        |
| 25886 BS30 | Exterior  | Paint/Coating (on West<br>Concrete Block Wall)                    | 1: Grey       | 100% Non-Fibrous                              | None Detected        |
| 25886 BS31 | Exterior  | Caulking (around West<br>Exterior Metal Door)                     | 1: Off-White  | 100% Non-Fibrous                              | None Detected        |
| 25886 BS32 | Exterior  | Caulking (around West<br>Exterior Metal Door)                     | 1: Off-White  | 100% Non-Fibrous                              | None Detected        |
| 25886 BS33 | Exterior  | Paint/Coating (on North<br>Concrete Block Wall)                   | 1: Grey       | 100% Non-Fibrous                              | None Detected        |
| 25886 BS34 | Exterior  | Concrete Block Mortar<br>(North Wall)                             | 1: Grey       | 100% Non-Fibrous                              | None Detected        |
| 25886 BS35 | Exterior  | Paint/Coating (on North<br>Concrete Block Wall)                   | 1: Grey       | 100% Non-Fibrous                              | None Detected        |
| 25886 BS36 | Exterior  | Caulking (where Concrete<br>Block Abuts North<br>Concrete Wall)   | 1: Grey       | 100% Non-Fibrous                              | None Detected        |
| 25886 BS37 | Exterior  | Paint/Coating (on East<br>Concrete Block Wall)                    | 1: Grey       | 100% Non-Fibrous                              | None Detected        |
| 25886 BS38 | Exterior  | Sealant (in South Exterior<br>Brown Metal-Framed<br>Window)       | 1: Black      | 95% Non-Fibrous                               | <b>5% Chrysotile</b> |
| 25886 BS39 | Exterior  | Caulking (around South<br>Exterior Brown Metal-<br>Framed Window) | 1: Grey       | 100% Non-Fibrous                              | None Detected        |
| 25886 BS40 | Exterior  | Paint/Coating (on South<br>Concrete Block Wall)                   | 1: White      | 100% Non-Fibrous                              | None Detected        |

Analyst(s): Oliver Collett

Sample(s) Collected on October 17, 2022

| Sample     | Location  | Description                                     | Layer: Colour | Non-Asbestos     | Asbestos      |
|------------|---|---|---------------|------------------|---------------|
|            |   |   |               | % Type           | % Type        |
| 25886 BS41 | Unit #4 - Ground Floor -<br>Entire Open Warehouse | Filling Compound on<br>Gypsum Board (East Wall) | 1: White      | 100% Non-Fibrous | None Detected |

| Sample     | Location  | Description  | Layer: Colour        | Non-Asbestos                                  | Asbestos      |
|------------|---|--|----------------------|---|---------------|
|            |   |  |                      | % Type  | % Type        |
| 25886 BS42 | Unit #4 - Ground Floor - Entire Open Warehouse                  | Caulking (around South Exterior Metal Door)            | 1: Grey              | 100% Non-Fibrous                              | None Detected |
| 25886 BS43 | Unit #4 - Ground Floor - Entire Open Warehouse                  | Filling Compound on Gypsum Board (West Wall)           | 1: White             | 100% Non-Fibrous                              | None Detected |
| 25886 BS44 | Unit #4 - Ground Floor - Entire Open Warehouse                  | Mastic (on Ductwork)                                   | 1: Grey              | 1% Cellulose<br>99% Non-Fibrous               | None Detected |
| 25886 BS45 | Unit #4 - Ground Floor - Washroom within Warehouse              | Floor Tile   | 1: Grey              | 100% Non-Fibrous                              | None Detected |
| 25886 BS46 | Unit #4 - Ground Floor - Washroom within Warehouse              | Floor Tile Adhesive                                    | 2: Black             | 100% Non-Fibrous                              | None Detected |
| 25886 BS47 | Unit #4 - Ground Floor - Washroom within Warehouse              | Paint<br>2' x 2' Ceiling Tile (Medium Fissure)         | 1: White<br>2: Grey  | 75% Cellulose<br>10% Glass<br>15% Non-Fibrous | None Detected |
| 25886 BS48 | Unit #4 - Ground Floor - Office (within Warehouse)              | Cove Base  | 1: Dark Brown        | 100% Non-Fibrous                              | None Detected |
| 25886 BS49 | Unit #4 - Ground Floor - Office (within Warehouse)              | Cove Base Adhesive                                     | 2: Beige             | 100% Non-Fibrous                              | None Detected |
| 25886 BS50 | Unit #8 - Ground Floor - South Open Office Area                 | Flooring Adhesive                                      | 1: Beige             | 100% Non-Fibrous                              | None Detected |
| 25886 BS51 | Unit #4 - Ground Floor - Open Office Area (including Reception) | Paint<br>Filling Compound on Gypsum Board (South Wall) | 1: Beige<br>2: White | 100% Non-Fibrous                              | None Detected |
| 25886 BS52 | Unit #4 - Ground Floor - Open Office Area (including Reception) | Paint<br>2' x 2' Ceiling Tile (Medium Fissure)         | 1: White<br>2: Grey  | 75% Cellulose<br>10% Glass<br>15% Non-Fibrous | None Detected |
| 25886 BS53 | Unit #4 - Ground Floor - Sprinkler Room                         | Pipe Thread Compound (at Fitting of Sprinkler Piping)  | 1: Black             | 1% Cellulose<br>99% Non-Fibrous               | None Detected |
| 25886 BS54 | Unit #4 - Ground Floor - Sprinkler Room                         | Flange Gasket  | 1: Red               | 100% Non-Fibrous                              | None Detected |
| 25886 BS55 | Unit #4 - Ground Floor - Sprinkler Room                         | Filling Compound on Gypsum Board (Ceiling)             | 1: White             | 100% Non-Fibrous                              | None Detected |
| 25886 BS56 | Unit #4 - Ground Floor - Northeast Office                       | Paint<br>2' x 2' Ceiling Tile (Medium Fissure)         | 1: White<br>2: Grey  | 75% Cellulose<br>10% Glass<br>15% Non-Fibrous | None Detected |
| 25886 BS57 | Unit #4 - Ground Floor - Northeast Office                       | Cove Base  | 1: Black             | 100% Non-Fibrous                              | None Detected |
| 25886 BS58 | Unit #4 - Ground Floor - Northeast Office                       | Cove Base Adhesive                                     | 2: Beige             | 100% Non-Fibrous                              | None Detected |

| Sample     | Location                             | Description                                      | Layer: Colour            | Non-Asbestos     | Asbestos      |
|------------|--------------------------------------|--|--------------------------|------------------|---------------|
|            |                                      |  |                          | % Type           | % Type        |
| 25886 BS59 | Unit #4 - Ground Floor - Washroom    | Floor Tile                                       | 1: Brown                 | 100% Non-Fibrous | None Detected |
| 25886 BS60 | Unit #4 - Ground Floor - Washroom    | Floor Tile Adhesive                              | 2: Black                 | 100% Non-Fibrous | None Detected |
| 25886 BS61 | Unit #4 - Ground Floor - Washroom    | Floor Tile                                       | 3: Grey                  | 100% Non-Fibrous | None Detected |
| 25886 BS62 | Unit #4 - Ground Floor - Washroom    | Floor Tile Adhesive                              | 4: Black                 | 100% Non-Fibrous | None Detected |
| 25886 BS63 | Unit #4 - Upper Floor - Boardroom    | Cove Base  | 1: Beige                 | 100% Non-Fibrous | None Detected |
| 25886 BS64 | Unit #4 - Upper Floor - Boardroom    | Cove Base Adhesive                               | 2: Off-White             | 100% Non-Fibrous | None Detected |
| 25886 BS65 | Unit #4 - Upper Floor - Break Room   | Coating (on Underside of Metal Sink)             | 1: Off-White             | 100% Non-Fibrous | None Detected |
| 25886 BS66 | Unit #4 - Upper Floor - Storage Room | Paint Filling Compound on Gypsum Board (Ceiling) | 1: Off-White<br>2: White | 100% Non-Fibrous | None Detected |

Analyst(s): Lolita Santos

Sample(s) Collected on October 18, 2022

| Sample     | Location  | Description  | Layer: Colour        | Non-Asbestos                                  | Asbestos      |
|------------|---|--|----------------------|---|---------------|
|            |   |  |                      | % Type  | % Type        |
| 25886 BS67 | Unit #8 - Ground Floor - South Open Office Area           | Flooring Adhesive Residue                          | 1: Black             | 100% Non-Fibrous                              | None Detected |
| 25886 BS68 | Unit #8 - Ground Floor - Entire Open Warehouse            | Paint Filling Compound on Gypsum Board (West Wall) | 1: White<br>2: White | 100% Non-Fibrous                              | None Detected |
| 25886 BS69 | Unit #8 - Ground Floor - South Open Area within Warehouse | Sheet Flooring                                     | 1: Blue              | 100% Non-Fibrous                              | None Detected |
| 25886 BS70 | Unit #8 - Ground Floor - South Open Area within Warehouse | Floor Adhesive                                     | 2: Grey              | 100% Non-Fibrous                              | None Detected |
| 25886 BS71 | Unit #8 - Ground Floor - South Open Area within Warehouse | 2' X 4' Ceiling Tile (Small Fissures, 2005)        | 1: Grey              | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected |
| 25886 BS72 | Unit #8 - Ground Floor - South Open Area within Warehouse | 2' X 4' Ceiling Tile (Large Fissures)              | 1: Grey              | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected |
| 25886 BS73 | Unit #8 - Ground Floor - South Open Area within Warehouse | Cove Base  | 1: Blue              | 100% Non-Fibrous                              | None Detected |

| Sample     | Location  | Description   | Layer: Colour       | Non-Asbestos                                  | Asbestos              |
|------------|---|---|---------------------|---|-----------------------|
|            |   |   |                     | % Type  | % Type                |
| 25886 BS74 | Unit #8 - Ground Floor - South Open Area within Warehouse                         | Cove Base Adhesive                                    | 2: Cream            | 100% Non-Fibrous                              | None Detected         |
| 25886 BS75 | Unit #8 - Ground Floor - South Office within Warehouse                            | Sealant (in West Interior Wood-Framed Window)         | 1: Black            | 5% Cellulose<br>95% Non-Fibrous               | None Detected         |
| 25886 BS76 | Unit #8 - Ground Floor - South Office within Warehouse                            | Floor Tile  | 1: Off-White        | 100% Non-Fibrous                              | None Detected         |
| 25886 BS77 | Unit #8 - Ground Floor - South Office within Warehouse                            | Floor Tile Adhesive                                   | 2: Beige            | 1% Cellulose<br>99% Non-Fibrous               | None Detected         |
| 25886 BS78 | Unit #8 - Ground Floor - South Office within Warehouse                            | Floor Tile  | 3: Grey             | 99% Non-Fibrous                               | 1% <b>Chrysotile</b>  |
| 25886 BS79 | Unit #8 - Ground Floor - South Office within Warehouse                            | Floor Tile Adhesive                                   | 4: Black            | 100% Non-Fibrous                              | None Detected         |
| 25886 BS80 | Unit #8 - Ground Floor - North Open Area within Warehouse                         | Floor Tile  | 1: Cream            | 99% Non-Fibrous                               | 1% <b>Chrysotile</b>  |
| 25886 BS81 | Unit #8 - Ground Floor - North Open Area within Warehouse                         | Floor Tile Adhesive                                   | 2: Black            | 100% Non-Fibrous                              | None Detected         |
| 25886 BS82 | Unit #8 - Ground Floor - North Open Area within Warehouse                         | Paint Filling Compound on Gypsum Board (North Wall)   | 1: White<br>2: Grey | 95% Non-Fibrous                               | 5% <b>Chrysotile</b>  |
| 25886 BS83 | Unit #8 - Ground Floor - North Open Area within Warehouse                         | 2' X 4' Ceiling Tile (Large Fissures)                 | 1: Grey             | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected         |
| 25886 BS84 | Unit #8 - Ground Floor - North Open Area within Warehouse                         | 2' X 4' Ceiling Tile (Medium Fissures)                | 1: Grey             | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected         |
| 25886 BS85 | Unit #8 - Ground Floor - North Open Area within Warehouse                         | Mastic (on Ductwork, Above T-Bar)                     | 1: Black            | 90% Non-Fibrous                               | 10% <b>Chrysotile</b> |
| 25886 BS86 | Unit #8 - Ground Floor - North Open Area within Warehouse                         | Mastic (on Ductwork, Above T-Bar)                     | 1: Black            | 90% Non-Fibrous                               | 10% <b>Chrysotile</b> |
| 25886 BS87 | Unit #8 - Ground Floor - 3 Adjoining West Offices within Warehouse - North Office | Paint Filling Compound on Gypsum Board (West Wall)    | 1: White<br>2: Grey | 98% Non-Fibrous                               | 2% <b>Chrysotile</b>  |
| 25886 BS88 | Unit #8 - Ground Floor - 3 Adjoining West Offices within Warehouse - North Office | Pipe Thread Compound (at Fitting of Sprinkler Piping) | 1: Beige            | 100% Non-Fibrous                              | None Detected         |

| Sample     | Location  | Description  | Layer: Colour | Non-Asbestos                                  | Asbestos       |
|------------|---|--|---------------|---|----------------|
|            |   |  |               | % Type  | % Type         |
| 25886 BS89 | Unit #8 - Ground Floor - 3 Adjoining West Offices within Warehouse - North Office | Insulating Cement (at Elbow of Mechanical Piping, Above T-Bar) | 1: White      | 80% Non-Fibrous                               | 20% Chrysotile |
| 25886 BS90 | Unit #8 - Ground Floor - 3 Adjoining West Offices within Warehouse - North Office | 2' X 4' Ceiling Tile (Large Fissures)                          | 1: Grey       | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected  |
| 25886 BS91 | Unit #8 - Ground Floor - 3 Adjoining West Offices within Warehouse - North Office | 2' X 4' Ceiling Tile (Medium Fissures)                         | 1: Grey       | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected  |
| 25886 BS92 | Unit #8 - Ground Floor - 3 Adjoining West Offices within Warehouse - North Office | 2' X 4' Ceiling Tile (Medium Fissures)                         | 1: Grey       | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected  |
| 25886 BS93 | Unit #8 - Ground Floor - Southeast Storage Room Within Warehouse                  | Caulking Patch (on West Concrete Block Wall)                   | 1: Grey       | 100% Non-Fibrous                              | None Detected  |
| 25886 BS94 | Unit #8 - Ground Floor - Southeast Storage Room within Warehouse                  | Caulking (around North Exterior Metal Door)                    | 1: Off-White  | 100% Non-Fibrous                              | None Detected  |

Analyst(s): Oliver Collett

#### Sample(s) Collected on October 19, 2022

| Sample      | Location  | Description  | Layer: Colour      | Non-Asbestos                                  | Asbestos      |
|-------------|---|--|--------------------|---|---------------|
|             |   |  |                    | % Type  | % Type        |
| 25886 BS95  | Unit #8 - Ground Floor - South Open Office Area | Cove Base  | 1: Brown           | 100% Non-Fibrous                              | None Detected |
| 25886 BS96  | Unit #8 - Ground Floor - South Open Office Area | Cove Base Adhesive                                 | 2: Cream           | 100% Non-Fibrous                              | None Detected |
| 25886 BS97  | Unit #8 - Ground Floor - South Open Office Area | Paint Filling Compound on Gypsum Board (East Wall) | 1: Grey<br>2: Grey | 97% Non-Fibrous                               | 3% Chrysotile |
| 25886 BS98  | Unit #8 - Ground Floor - South Open Office Area | 2' X 4' Ceiling Tile (Small Fissures)              | 1: Grey            | 65% Cellulose<br>20% Glass<br>15% Non-Fibrous | None Detected |
| 25886 BS99  | Unit #8 - Ground Floor - South Open Office Area | Sealant (in Window of West Interior Wood Door)     | 1: Black           | 2% Cellulose<br>98% Non-Fibrous               | None Detected |
| 25886 BS100 | Unit #8 - Ground Floor - South Open Office Area | Sealant (in East Interior Wood-Framed Window)      | 1: Black           | 95% Non-Fibrous                               | 5% Chrysotile |
| 25886 BS101 | Unit #8 - Ground Floor - Telecom Room           | Floor Tile   | 1: Grey            | 100% Non-Fibrous                              | None Detected |
| 25886 BS102 | Unit #8 - Ground Floor - Telecom Room           | Floor Tile Adhesive                                | 2: Black           | 100% Non-Fibrous                              | None Detected |

| Sample      | Location  | Description  | Layer: Colour | Non-Asbestos                     | Asbestos              |
|-------------|---|--|---------------|----------------------------------|-----------------------|
|             |   |  |               | % Type                           | % Type                |
| 25886 BS103 | Unit #8 - Ground Floor - Telecom Room                     | Cove Base  | 1: Grey       | 100% Non-Fibrous                 | None Detected         |
| 25886 BS104 | Unit #8 - Ground Floor - Telecom Room                     | Cove Base Adhesive                                   | 2: Beige      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS105 | Unit #8 - Ground Floor - Telecom Room                     | Sealant (in Window of South Interior Wood Door)      | 1: White      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS106 | Unit #8 - Ground Floor - Southeast Office                 | Floor Tile   | 1: Blue       | 100% Non-Fibrous                 | None Detected         |
| 25886 BS107 | Unit #8 - Ground Floor - Southeast Office                 | Floor Tile Adhesive                                  | 2: Black      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS108 | Unit #8 - Ground Floor - Southeast Office                 | Floor Tile   | 1: Beige      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS109 | Unit #8 - Ground Floor - Southeast Office                 | Floor Tile Adhesive                                  | 2: Black      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS110 | Unit #8 - Ground Floor - Southeast Office                 | Cove Base  | 1: Brown      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS111 | Unit #8 - Ground Floor - Southeast Office                 | Cove Base Adhesive                                   | 2: Brown      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS112 | Unit #8 - Ground Floor - Southeast Office                 | Mastic (on Ductwork)                                 | 1: Black      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS113 | Unit #8 - Ground Floor - Southwest Hallway                | Floor Tile   | 1: Grey       | 100% Non-Fibrous                 | None Detected         |
| 25886 BS114 | Unit #8 - Ground Floor - Southwest Hallway                | Floor Tile Adhesive                                  | 2: Beige      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS115 | Unit #8 - Ground Floor - Loading Bay                      | Insulating Cement (at Elbow of Mechanical Piping)    | 1: White      | 85% Non-Fibrous                  | <b>15% Chrysotile</b> |
| 25886 BS116 | Unit #8 - Ground Floor - South Break Room                 | Coating (on Underside of Metal Sink)                 | 1: Off-White  | 20% Cellulose<br>80% Non-Fibrous | None Detected         |
| 25886 BS117 | Unit #8 - Ground Floor - South Men's and Women's Washroom | Sheet Flooring Residue                               | 1: Blue       | 1% Cellulose<br>99% Non-Fibrous  | None Detected         |
| 25886 BS118 | Unit #8 - Ground Floor - First Aid Room                   | Filling Compound Patch (on West Concrete Block Wall) | 1: White      | 100% Non-Fibrous                 | None Detected         |
| 25886 BS119 | Unit #8 - Ground Floor - North Break Room                 | Coating (on Underside of Metal Sink)                 | 1: Gold       | 98% Non-Fibrous                  | <b>2% Chrysotile</b>  |
| 25886 BS120 | Unit #8 - Ground Floor - North Break Room                 | 12"Ceiling Tile                                      | 1: Brown      | 85% Cellulose<br>15% Non-Fibrous | None Detected         |
| 25886 BS121 | Unit #8 - Ground Floor - North Break Room                 | 12"Ceiling Tile                                      | 1: Brown      | 85% Cellulose<br>15% Non-Fibrous | None Detected         |
| 25886 BS122 | Unit #8 - Ground Floor - North Break Room                 | 12"Ceiling Tile                                      | 1: Brown      | 85% Cellulose<br>15% Non-Fibrous | None Detected         |
| 25886 BS123 | Unit #8 - Ground Floor - North Open Office Area           | Floor Tile   | 1: Brown      | 98% Non-Fibrous                  | <b>2% Chrysotile</b>  |

| Sample      | Location  | Description         | Layer: Colour | Non-Asbestos     | Asbestos      |
|-------------|---|---------------------|---------------|------------------|---------------|
|             |   |                     |               | % Type           | % Type        |
| 25886 BS124 | Unit #8 - Ground Floor - North Open Office Area | Floor Tile Adhesive | 2: Black      | 100% Non-Fibrous | None Detected |

Analyst(s): Oliver Collett

Sample(s) Collected on October 20, 2022

| Sample      | Location   | Description   | Layer: Colour        | Non-Asbestos                | Asbestos      |
|-------------|--|---|----------------------|-----------------------------|---------------|
|             |  |   |                      | % Type                      | % Type        |
| 25886 BS125 | Exterior   | Caulking (around East Exterior Metal Door)                                    | 1: Grey              | 95% Non-Fibrous             | 5% Chrysotile |
| 25886 BS126 | Exterior   | Firestop Grout (at East Wall Penetration of Electrical Cable)                 | 1: Grey              | 100% Non-Fibrous            | None Detected |
| 25886 BS127 | Exterior   | Caulking (around East Metal Exhaust Vent)                                     | 1: Grey              | 3% Glass<br>97% Non-Fibrous | None Detected |
| 25886 BS128 | Exterior   | Firestop Caulking (at Former East Wall Penetration of Electrical Cable)       | 1: White             | 100% Non-Fibrous            | None Detected |
| 25886 BS129 | Exterior   | Paint/Coating (on East Concrete Block Wall)                                   | 1: Beige             | 100% Non-Fibrous            | None Detected |
| 25886 BS130 | Exterior   | Paint/Coating (on East Concrete Block Wall)                                   | 1: Beige             | 100% Non-Fibrous            | None Detected |
| 25886 BS131 | Exterior   | Paint/Coating (on East Concrete Block Wall)                                   | 1: Beige             | 100% Non-Fibrous            | None Detected |
| 25886 BS132 | Exterior   | Caulking Patch (on East Concrete Block Wall)                                  | 1: White             | 100% Non-Fibrous            | None Detected |
| 25886 BS133 | Unit #8 - Ground Floor - 4 Adjoining North Offices | Paint Filling Compound on Gypsum Board (Inner Layer, North Wall, East Office) | 1: White<br>2: Grey  | 97% Non-Fibrous             | 3% Chrysotile |
| 25886 BS134 | Unit #8 - Ground Floor - 4 Adjoining North Offices | Filling Compound (Residue on Floor, East Office)                              | 1: White             | 97% Non-Fibrous             | None Detected |
| 25886 BS135 | Unit #8 - Ground Floor - 4 Adjoining North Offices | Adhesive (on Back of Gypsum Board, North Wall, East Office)                   | 1: White             | 100% Non-Fibrous            | None Detected |
| 25886 BS136 | Unit #4 - Upper Floor - Computer Room              | Paint Filling Compound on Gypsum Board (South Wall)                           | 1: White<br>2: White | 100% Non-Fibrous            | None Detected |

Analyst(s): Lolita Santos



American Industrial Hygiene Association (AIHA) Bulk Asbestos Proficiency Analytical Testing (BAPAT)  
Astech Consultants Ltd. Laboratory Participant ID# 200542



## LEAD BULK SAMPLE REPORT

Date: October 27, 2022  
Client: TDK METRO TERMINALS  
Location: Multi-Tenant Warehouse/Storage Building  
480 Audley Boulevard  
Delta, BC

Comments: 1) The Workers' Compensation Board of British Columbia (WCB) no longer allows reference to Health Canada's definition of a lead-containing surface coating material.  
2) WCB does not define a safe level for a lead-containing surface coating material.  
3) Analyzed by X-Ray Fluorescence (XRF) with direct read parts per million (PPM).  
4) Sample results report lead only.  
5) < means less than, > means more than.  
6) Samples will be disposed of after 90 days, unless the Client requests otherwise.

Sample(s) Collected on October 13, 2022

| Sample     | Location                                       | Description                          | Colour        | Lead PPM |
|------------|--|--------------------------------------|---------------|----------|
| 25886 LS01 | Unit #10 - Ground Floor - South Open Warehouse | Paint (on North Wood Wall)           | Green on Blue | 243 PPM  |
| 25886 LS02 | Unit #10 - Ground Floor - South Open Warehouse | Paint (on North Concrete Block Wall) | Blue          | 22 PPM   |
| 25886 LS03 | Unit #10 - Ground Floor - South Open Warehouse | Paint (on North Concrete Block Wall) | White         | < 13 PPM |
| 25886 LS04 | Unit #10 - Ground Floor - South Open Warehouse | Paint (on East Metal Bollard)        | Black         | < 9 PPM  |
| 25886 LS05 | Exterior                                       | Paint (on West Concrete Block Wall)  | White         | 53 PPM   |
| 25886 LS06 | Exterior                                       | Paint (on West Concrete Block Wall)  | Yellow        | 15 PPM   |
| 25886 LS07 | Exterior                                       | Paint (on West Concrete Wall)        | Grey          | 31 PPM   |

Analyst(s): Jessica Young



## Sample(s) Collected on October 17, 2022

| Sample     | Location                             | Description                    | Colour    | Lead    |
|------------|--------------------------------------|--------------------------------|-----------|---------|
|            |                                      |                                |           | PPM     |
| 25886 LS08 | Unit #4 - Upper Floor - Storage Room | Paint (on East Wood Door Trim) | Grey      | < 9 PPM |
| 25886 LS09 | Unit #4 - Upper Floor - Storage Room | Paint (on Gypsum Board Wall)   | Off-White | < 8 PPM |

Analyst(s): Jessica Young

## Sample(s) Collected on October 18, 2022

| Sample     | Location  | Description               | Colour       | Lead   |
|------------|---|---------------------------|--------------|--------|
|            |   |                           |              | PPM    |
| 25886 LS10 | Unit #8 - Ground Floor - Southeast Storage Room<br>Within Warehouse | Paint (on Concrete Floor) | Grey on Blue | 28 PPM |

Analyst(s): Jessica Young

## Sample(s) Collected on October 19, 2022

| Sample     | Location                                | Description                      | Colour | Lead    |
|------------|---|----------------------------------|--------|---------|
|            |   |                                  |        | PPM     |
| 25886 LS11 | Unit #8 - Ground Floor - Loading Bay    | Paint (on East Wood Window Trim) | White  | 131 PPM |
| 25886 LS12 | Unit #8 - Ground Floor - First Aid Room | Paint (on North Wood Door Trim)  | Beige  | 647 PPM |

Analyst(s): Jessica Young



Certified to ISO:20807; and Health Canada's and Natural Resources Canada's requirements for compliance with Health Canada Safety Code 32 & 34